

Junction City Sundowner Snowmobile Club Mechanic Contact Info				Dates Worked				
First Name	Last Name	Email	phone	1/24	1/31	2/2	2/7	2/14
Todd	Adams	traceyandtodd@gmail.com						
Andrew	Bernhagen	andybernhagen@gmail.com	608-512-2593					
Matt	Bertz	mbertz@tds.net	715-571-0020	X	X			X
Jim	Demski	jdemski@g2a.net	715-344-3288		X		X	X
Cole	Fourness	cfourness95@gmail.com	715-498-9879				X	
Scott	Goeb	smgabe@tds.net	715-340-4521					
Joshua	Gross	jmgfsh4evr@gmail.com	715-340-9205	X	X	X	X	X
Todd	Koch	fordsrus64@solarus.net	715-323-2195		X	X		
Joe	Kvatek		715-570-1083	X				
Jamey	Palbrach	palbrach@charter.net	715-340-9539	X	X			X
Dan	Pepper	outlander06800@yahoo.com	715-321-2914		X			
Andy	Ponshock	andy.ponshock@gmail.com	715-572-5666					
Phil	Prust	prust30@gmail.com	715-305-2837		X		X	
Kevin	Rabska	krabska@horizonglobal.com	715-340-1268	X		X	X	X
Steve	Schulfer	psschulfer@wi-net.com	715-459-6824	X	X	X		
Anthony	Simkowski	simmy201@gmail.com	715-340-9578	X				
Tim	Sobczak	sobie7@tznnet.com	715-459-6999					
Travis	Sobczak	soby@tds.net	715-340-2773					
Andrew	Soucek	asoucek@sbcglobal.net	715-340-3013		X			
Bob	Szymkowiak	polkabob69@yahoo.com	715-340-1318		X			
Jim	Zarecki	jbz@tds.net	715-457-2808		X		X	
21				33				

Complete:

- 1 Matt, Jim, Josh, Jamey & Kevin reversed belting on both tracks to be matching.
- 2 New muffler tack welded together, will be finish welded by Jamey.
- 3 Axle and sprockets back from Utah by 2/24.
- 4 Cole & Phil repaired wiring on John Deere
- 5 Steve made new hardware for plow.
- 6 Steve replaced hydro pump for cab lift.
- 7 Kevin & Jim cleaned and inspected all wheel bearings
- 8 Jim & Josh tightened many loose bolts and hydro fittings
- 9 Travis welded frame rail on John Deere Soucy track
- 10 Todd welded spindles on LMC
- 11 Dan donated degreaser to clean undercarriage of machine.
- 12 Josh donated hydro die to assist in finding leaks
- 13 Dean donating tools and shop space

Repairs Needed:

- 1 Rear LED lights not working.
- 2 Move hydraulic coolant to rear of machine.
- 3 Rear antenna falling off
- 4 Clean replace or repair radiator.
- 5 Install plow hardware.
- 6 Change fluid in rear drive hubs.
- 7 Consider alternate mounting location for cab lift hydraulic unit.
- 8 Still leaking hydro fluid, seems to be a lot from under the tank.
- 9 Install wheel bearings and seals.
- 10 Install wipers
- 11 Repair primer pump